

# CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1a.1 Cannot Assemble

Physical Phenomenon : **Spatter in Weld Nut**

Before



100 % VISUAL INSPECTION

After



100 % INSPECTION BY BOLT