


CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD




1a.3 Cannot Assemble

Physical Phenomenon : **Spatter in Holes**

Before



After



100 % INSPECTION BY PIN