


CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1a.4 Cannot Assemble


Physical Phenomenon : **Spatter on studs**

Before



SAMPLE INSPECTION BY TOUCH & FEEL

After



100 % INSPECTION BY RING GAUGE