

CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1a.5 Cannot Assemble

Physical Phenomenon : **Spatter on surface**

Before

After

100% VISUAL
INSPECTION



100 % INSPECTION BY TOUCH & FEEL