

CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1a.6 Cannot Assemble

Physical Phenomenon : **Wrong Part**

Before



M5 NUT WELDED IN PLACE OF M6 NUT

After



100% INSPN. BY THREAD PLUG GAUGE