

# CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1a.8 Cannot Assemble


Physical Phenomenon : **Part Missing**

Before



100 % VISUAL INSPECTION & COUNTING

After



100 % INSPECTION BY SENSING "PART PRESENCE"