


CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1a.9 Cannot Assemble

Physical Phenomenon : **Part Missing**

After



PART SENSORS

After



LED INDICATORS ON WHEN PART MISSING