

CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1a.10 Cannot Assemble

Physical Phenomenon : **Hole Missing**

Before



100% BY VISUAL CHECKING

After



100% BY LASER MACHINE