


CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1a.11 Cannot Assemble

Physical Phenomenon : **Wrong Position due Shift**

Before



SAMPLE INSPECTION WITH
MEASURING TAPE

After



100 % INSPECTION BY RELATION
GAUGE