

CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD




1a.13 Cannot Assemble

Physical Phenomenon : **Wrong Mounting Position due to Twist**

Before

After

SAMPLING INSPECTION



BY RELATION GAUGE

100 % INSPECTION BY RELATION GAUGE