

POKA-YOKE

POKA YOKE SHEET		NTTF Industries Ltd.		
PROBLEM: MIXUP OF BOTH MODELS BODY	INDICATE *		Shutdown	
SOLUTION: DATE STAMPING FIXTURE MODIFIED	Prevent error		control	
KEY IMPROVEMENT:	detect error		Alarm	
BEFORE		AFTER		
				