



POKA – YOKE SHEET

Problem:- Rejection of GPL 112 in bending operation.

Solution:- LOCATOR ADDED.

Key Improvement:- ZERO REJECTION.

YES

Prevent Error

Shut Down

YES

Control

YES

Detect Error

Alarm

BEFORE

AFTER



LOCATOR