

# CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1a.2 Cannot Assemble

Physical Phenomenon : **Spatter in Weld Nut**

Before

After

SAMPLING  
INSPECTION



BY THREAD PLUG GAUGE

100 % INSPECTION BY THREAD PLUG GAUGE