

CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1d.1 Leakage

Physical Phenomenon : **Improper Sealing Due to Spatter on face**

Before

100% VISUAL INSPECTION

VISUAL CHECK FOR SPATTER ON FACE

After



100 % INSPECTION FOR AIR LEAKAGE
BY DIPPING IN WATER