

# CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



## 1d.2 Leakage

Physical Phenomenon : **Incomplete welding**

Before



100 % VISUAL INSPECTION FOR HOLES / INCOMPLETE WELDING (PIN HOLES NOT DETECTABLE)

After



100 % BY AIR LEAKAGE TESTING (EVEN MINOR PIN HOLE IS DETECTABLE)