

CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1e.2 Weld Strength Poor


Physical Phenomenon : **Weak Spot**

Before

After

After

NO INSPECTION



SAMPLE INSPECTION - NUGGET TESTING (COUPON TEST)
FOR PULL OUT STRENGTH BY TENSOMETER