


# Poka-yoke Sheet

<b>Problem:</b> MISSING OF OPERATION DUE TO TOOL BREAKAGE	Prevent Error		Shutdown	
<b>Solution:</b> PINS ARE PROVIDED TO CHECK FOR THE OPENING OUT OF THE HOLES	Detect Error	★	Control	
			Alarm	★

**Key Improvement:** CHECKING OF THE CIRCUIT IN THE FINAL STAGE, WHICH HAPPENS TO BE THE BOTTLE NECK CAN BE ELIMINATED

Before



After

