

IN HOUSE REJECTION: KAIZEN

3a.10 Appearance not Good

Physical Phenomenon : **shabby welding**
Due to : Man / **Machine** / Method / Material

Before

After

Variable wire feed & Current.

Kaizen Idea : No current variation.



Root Cause : Current varies from 200 to 260 Amps.

Kaizen : Additional resistance provided in machine.