

CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1a.7 Cannot Assemble

Physical Phenomenon : **Part Missing**

Before

After

No Inspection



100 % INSPECTION FOR "PRESENCE OF PARTS"
THROUGH CHECK SHEET & TICKING FOR CONFIRMATION