

CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1c Noise

Physical Phenomenon : **Loose Spatter inside**

Before

After

NO INSPECTION



NO INSPECTION

100 % INSPECTION BY MANUAL SHAKING OF COMPONENT