

CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1b.3 Appearance not good

Physical Phenomenon : **Dent**

Before

After

SAMPLING INSPECTION



VISUAL INSPECTION

100 % VISUAL INSPECTION
& MARKING