

CUSTOMER COMPLAINT - CHANGE IN INSPECTION METHOD



1b.6 Appearance not good

Physical Phenomenon : **Shabby Welding**

Before



After



VISUAL INSPECTION

100 % VISUAL INSPECTION